We are IntechOpen, the world's leading publisher of Open Access books Built by scientists, for scientists

6,300

Open access books available

172,000

International authors and editors

190M

Downloads

Our authors are among the

154

Countries delivered to

TOP 1%

most cited scientists

12.2%

Contributors from top 500 universities

WEB OF SCIENCE™

Selection of our books indexed in the Book Citation Index
in Web of Science™ Core Collection (BKCI)

Interested in publishing with us?
Contact book.department@intechopen.com

Numbers displayed above are based on latest data collected.
For more information visit www.intechopen.com

Plant identification by relay method

Miluše Vítečková and Antonín Víteček
VŠB – Technical University of Ostrava
Czech Republic

1. Introduction

Plant identification is very important in control design. The relay method belongs among special kinds of experimental frequency response identification. It was originally used for plant identification by Rotach (Rotač, 1964) and lately also for controller autotuning, see reference (Åström & Wittenmark, 1989; Åström, 1993; Åström & Hägglund, 1995; Bi et al., 1997; Hang et al., 1993; Lu et al., 1998; Shen et al., 1999; Tan et al., 1996; Wang et al., 1999). Autotuning of controllers for MIMO plants is described in references (Halevi et al., 1997; Loh & Vasnani, 1994; Semino & Scali, 1998). At present more publications exist which are devoted to identification or controller autotuning on the basis of the relay experiment, e.g. (Besançon-Voda & Roux-Buisson, 1997; Hang et al., 2002; Huang et al. 2005; Johnson & Moradi, 2005; Kaya & Atherton, 2001; Lee et al., 1995; Leva & Donida, 2009; Leva & Maggio, 2009; Liu & Gao, 2009; Majhi, 2005; Majhi, 2007; Panda & Yu, 2003; Panda & Yu, 2005; Prokop et al., 2010; Sung et al., 2009; Tan et al., 2001; Tan et al., 2002; Vítečková & Víteček, 2005; Vivek & Chidambaram, 2005).

The aim of this paper is to summarily describe and show the basic modifications of the relay methods from the viewpoint of experimental plant identification and to bring out the computational formulas for simple plants. Two-position symmetric relays without and with hysteresis and with the integrator in front of the relay and behind of the relay are considered.

2. Relay Method without Integrator

In experimental plant identification using the relay method without the integrator it is assumed that the relay is plugged into the closed-loop system in lieu of a controller in accordance with Fig. 1, where: e , w , u and y are the control error, desired, manipulated and controlled variables, $G_p(s)$ – the plant transfer function, $N(a)$ – the describing function of the relay (Fig. 2), s – the complex variable in L-transform, a – the harmonic oscillation amplitude.

Fig. 1. Closed-loop system with two-position relay

The relay role is to effect stable oscillations of the closed-loop system in Fig. 1, i.e. to cause rise of the stable limit cycle. The describing function method is suitable to verify the limit cycle rise (Vukić et al., 2003). The describing function of the relay $N(a)$ can be considered as the complex gain which depends on the harmonic oscillation amplitude a with the angular frequency ω

$$e(t) = a \sin \omega t \quad (1)$$

in the relay input and therefore it is possible to work with it like a common transfer function.

The condition of the limit cycle rise of the non-linear closed-loop system in Fig. 1 has the simple form

$$G_p(j\omega) = -\frac{1}{N(a)} \quad (2)$$

$$G_p(j\omega) = A_p(\omega) e^{j\varphi_p(\omega)} \quad (3)$$

where $G_p(j\omega)$ is the plant transfer function in the frequency domain, $A_p(\omega)$ - the plant transfer function magnitude, $\varphi_p(\omega)$ - the plant transfer function phase.

The relation (2) is in analogy with the stability boundary for the linear control system

$$G_o(j\omega) = -1 \quad (4)$$

where $G_o(j\omega)$ is the open-loop control system transfer function in the frequency domain.

Fig. 2. Two-position symmetric relay: a) with hysteresis, b) without hysteresis

From comparison of the relations (2) and (4) it is obvious that the term $-1/N(a)$ has the same role as the critical point -1 for the linear control systems and therefore it is called a critical characteristic.

For the two-position symmetric relay with hysteresis ($\varepsilon > 0$, Fig. 2a) or without hysteresis ($\varepsilon = 0$, Fig. 2b) the describing function and the corresponding critical characteristic have the forms (Vukić et al., 2003)

$$N(a) = \begin{cases} \frac{4u_0}{\pi i} \left[\sqrt{1 - \left(\frac{\varepsilon}{a}\right)^2} - j\frac{\varepsilon}{a} \right] & \text{for } 0 \leq \varepsilon < a \\ 0 & \text{for } 0 \leq a < \varepsilon \end{cases} \quad (5)$$

$$-\frac{1}{N(a)} = \begin{cases} A_N(a)e^{j\varphi_N(a)} & \text{for } 0 \leq \varepsilon < a \\ -\infty & \text{for } 0 \leq a < \varepsilon \end{cases} \quad (6a)$$

$$A_N(a) = \frac{\pi i}{4u_0} \quad (6b)$$

$$\varphi_N(a) = -\pi + \operatorname{arctg} \frac{\varepsilon}{\sqrt{a^2 - \varepsilon^2}} \quad (6c)$$

where 2ε is the hysteresis width, u_0 – the relay amplitude (maximum value of the manipulated variable u), $A_N(a)$ – the critical characteristic magnitude, $\varphi_N(a)$ – the critical characteristic phase.

Because the describing function (5) uses only the fundamental harmonic component of the oscillation at the relay input, therefore the describing function method is the approximate method, which gives more accurate results if the behaviour of the plant with the transfer function $G_P(s)$ is close to behaviour of a low-pass filter (Vukić et al., 2003).

The condition represents the complex equation (2) can be substituted by two generally nonlinear equations

$$\begin{aligned} A_P(\omega) &= A_N(a) \\ \varphi_P(\omega) &= \varphi_N(a) \end{aligned} \quad (7)$$

By solving of (7) the amplitude a_M and the angular frequency ω_M can be obtained. If the obtained values a_M and ω_M are positive and real, then in the closed-loop system in Fig. 1, the stable limit cycle rises with the oscillation amplitude a_M at the relay input and with the angular frequency ω_M (Vukić et al., 2003).

The geometric interpretation of the solution of the complex equation (2) or the two real equations (7) is given in Fig. 3. The arrows of the curve $G_P(j\omega)$ and the critical characteristic (6) show the directions of the growth of the angular frequency ω and the harmonic oscillation amplitude a at the relay input (1).

Fig. 3. Geometric interpretation of relay method without integrator

If in the closed-loop system in Fig. 1 the stable limit cycle rises, then from the measured values a_M and ω_M on the basis of the equations (7) is possible to obtain two unknown plant parameters, see Fig. 4.
For $w(t) = 0$ the plant output variable $y(t)$ (except for sign) is the relay input variable $e(t)$, the equality

$$a_M = a_y \tag{8}$$

holds and the angular frequency ω_M is the same for all closed-loop system variables and it can be determined from the formula

$$\omega_M = \frac{2\pi}{T_y} \tag{9}$$

Fig. 4. Courses of relay output variable $u(t)$ and plant output variable $y(t)$ in the case of stable limit cycle rise

An application of the relay with hysteresis is useful in the case of existence of noise. In this case it is recommended so as to hysteresis width 2ε was greater then double noise amplitude and the relay amplitude u_0 should be such so as to output plant variable amplitude a_y was at least triple noise amplitude (Hang et al., 1993). Between the output oscillation amplitude a_y and the relay amplitude u_0 a direct proportion holds.

For the relay with hysteresis the angular frequency (9) is lower then for the relay without hysteresis.

From Fig. 3 it is obvious that the relay method without the integrator is suitable for proportional and integral plants with time delay. The plant gain can be determined from the steady state or by the other corresponding way. For the relay without hysteresis the equality $\omega_M = \omega_{-\pi}$ holds.

Example 2.1

For the proportional plant with transfer function

$$G_P(s) = \frac{k_1}{(T_i s + 1)^i} e^{-T_{di}s} \quad (10)$$

it is necessary to determine the plant time constant T_i and plant time delay T_{di} on condition that the plant gain k_1 and plant order i are known, using the relay method without integrator.

Solution:

For plant (10) the relations

$$G_P(j\omega) = \frac{k_1}{(jT_i\omega + 1)^i} e^{-jT_{di}\omega} = A_P(\omega) e^{j\varphi_P(\omega)} \quad (11a)$$

$$A_P(\omega) = \frac{k_1}{(1 + \omega^2 T_i^2)^{\frac{i}{2}}} \quad (11b)$$

$$\varphi_P(\omega) = -[\omega T_{di} + i \arctg(\omega T_i)] \quad (11c)$$

hold.

From experimentally obtained periodic course of the output variable $y(t)$ the oscillation amplitude a_y and period T_y can be measured (see Fig. 4), and than on the basis of the relations (6b), (6c), (7), (8), (9), (11b) and (11c) for $a = a_M = a_y$ and $\omega = \omega_M$ the formulas

$$T_i = \frac{T_y}{2\pi} \sqrt[i]{ \sqrt{ \frac{16k_1^2 u_0^2}{\pi^2 a_y^2} } - 1 } \quad (12a)$$

$$T_{di} = \frac{T_y}{2\pi} \left[\pi - i \operatorname{arctg} \frac{2\pi T_i}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (12b)$$

can be obtained.

E.g. for a proportional (first order plus time delay) plant with the transfer function

$$G_p(s) = \frac{k_1}{T_1 s + 1} e^{-T_{d1}s} \quad (13a)$$

from formulas (12) for $i = 1$ can be obtained

$$T_1 = \frac{T_y}{2\pi} \sqrt{\frac{16k_1^2 u_0^2}{\pi^2 a_y^2} - 1} \quad (13b)$$

$$T_{d1} = \frac{T_y}{2\pi} \left[\pi - \operatorname{arctg} \frac{2\pi T_1}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (13c)$$

Likewise for a proportional (second order plus time delay) plant with the transfer function

$$G_p(s) = \frac{k_1}{(T_2 s + 1)^2} e^{-T_{d2}s} \quad (14a)$$

from formulas (12) for $i = 2$ can be obtained

$$T_2 = \frac{T_y}{2\pi} \sqrt{\frac{4k_1 u_0}{\pi a_y} - 1} \quad (14b)$$

$$T_{d2} = \frac{T_y}{2\pi} \left[\pi - 2 \operatorname{arctg} \frac{2\pi T_2}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (14c)$$

Notice:

The plant (10) parameters T_i and T_{di} for known k_1 and i can also be determined from the ultimate (critical) gain of a proportional controller k_{pc} and the ultimate (critical) period T_c it holds

$$T_i = \frac{T_c}{2\pi} \sqrt{i \sqrt{k_{pc}^2 k_1^2} - 1} \quad (15a)$$

$$T_{di} = \frac{T_c}{2\pi} \left(\pi - i \operatorname{arctg} \frac{2\pi T_i}{T_c} \right) \quad (15b)$$

The ultimate controller gain k_{pc} and the corresponding ultimate period T_c , must be determined iteratively. In this case formulas (15) are exact and therefore the accuracy of the determined parameters T_i and T_{di} is considerably higher.

Example 2.2

Likewise in the example 2.1 on the basis of the relay method (without the integrator) for the integral plant with the transfer function

$$G_p(s) = \frac{k_1}{s(T_i s + 1)^i} e^{-T_{di}s} \quad (16)$$

it is necessary to determine the plant time constant T_i and plant time delay T_{di} on condition that the plant gain k_1 and order i are known.

Solution:

For the plant (16) on the basis of the relations (11) it can be written directly

$$A_p(\omega) = \frac{k_1}{\omega(1 + \omega^2 T_i^2)^{\frac{i}{2}}} \quad (17a)$$

$$\varphi_p(\omega) = -\left[\frac{\pi}{2} + \omega T_{di} + i \arctg(\omega T_i)\right] \quad (17b)$$

For experimentally obtained plant oscillation amplitude a_y and period T_y (see Fig. 4), and than on the basis of the relations (6b), (6c), (7), (8), (9), (17a) and (17b) for $a = a_M = a_y$ and $\omega = \omega_M$ the formulas

$$T_i = \frac{T_y}{2\pi} \sqrt[i]{\frac{4k_1^2 T_y^2 u_0^2}{\pi^4 a_y^2} - 1} \quad (18a)$$

$$T_{di} = \frac{T_y}{2\pi} \left[\frac{\pi}{2} - i \arctg \frac{2\pi T_i}{T_y} - \arctg \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (18b)$$

can be obtained.

E.g. for the integral (integral plus first order plus time delay) plant with the transfer function

$$G_p(s) = \frac{k_1}{s(T_1 s + 1)} e^{-T_{d1}s} \quad (19a)$$

from the formulas (18) for $i = 1$ can be obtained

$$T_1 = \frac{T_y}{2\pi} \sqrt{\frac{4k_1^2 T_y^2 u_0^2}{\pi^4 a_y^2} - 1} \quad (19b)$$

$$T_{d1} = \frac{T_y}{2\pi} \left[\frac{\pi}{2} - \operatorname{arctg} \frac{2\pi T_1}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (19c)$$

Likewise for the integral (integral plus second order plus time delay) plant with the transfer function

$$G_p(s) = \frac{k_1}{s(T_2 s + 1)^2} e^{-T_{d2}s} \quad (20a)$$

from the formula (18) for $i = 2$ can be obtained

$$T_2 = \frac{T_y}{2\pi} \sqrt{\frac{2k_1 T_y u_0}{\pi^2 a_y} - 1} \quad (20b)$$

$$T_{d2} = \frac{T_y}{2\pi} \left[\frac{\pi}{2} - 2 \operatorname{arctg} \frac{2\pi T_2}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{a_y^2 - \varepsilon^2}} \right] \quad (20c)$$

Notice:

As well in this case the plant (16) parameters T_i and T_{di} for known k_1 and i can be determined from the ultimate controller gain k_{pc} and the ultimate period T_c , it holds that

$$T_i = \frac{T_c}{2\pi} \sqrt[i]{\frac{k_{pc}^2 k_1^2 T_c^2}{4\pi^2} - 1} \quad (21a)$$

$$T_{di} = \frac{T_c}{2\pi} \left(\frac{\pi}{2} - i \operatorname{arctg} \frac{2\pi T_i}{T_c} \right) \quad (21b)$$

The formulas (21) are exact, but the ultimate controller gain k_{pc} and the corresponding ultimate period T_c must be determined iteratively.

3. Relay Method with Integrator

The relay method with integrator is extending the previous approach (Åström & Hägglund 1995). It can be used in two alternatives: with the integrator behind of the relay (Fig. 5a) and with the integrator in front of the relay (Fig. 5b). Both these alternatives must be strictly differentiated. For both alternatives in Fig. 5 the condition of the stable limit rise has a form [compare with (2)]

$$\frac{1}{j\omega} G_p(j\omega) = -\frac{1}{N(a)} \quad (22)$$

and can be substituted by two equations [compare with (7)]

$$\frac{1}{\omega} A_P(\omega) = A_N(a)$$
$$\varphi_P(\omega) - \frac{\pi}{2} = \varphi_N(a)$$

(23)

Fig. 5. Closed-loop system with relay with integrator: a) behind of relay, b) in front of relay

Fig. 6. Geometric interpretation of relay method with integrator

If the solution, i.e. the values $a = a_M$ and $\omega = \omega_M$, are positive and real (Fig. 6), then in the closed-loop systems in Fig. 5 the stable limit cycle rises with the oscillation amplitude a_M and the angular frequency ω_M at the relay input.

From Fig. 6 it is obvious that the relay method with the integrator is applicable only for proportional plants. For the relay without hysteresis with the integrator the relation $\omega_M = \omega_{-\pi/2}$ holds.

a) Integrator is behind the relay

In this case for $w(t) = 0$ the output plant variable $y(t)$ (except for sign) is the input relay variable $e(t)$, and therefore (8) holds, i.e. $a_M = a_y$.

Example 3.1

For the plant (10) from the example 2.1 it is necessary when using the relay method with the integrator behind the relay, to determine the plant time constant T_i and plant time delay T_{di} on condition that the plant gain k_1 and its order i are known.

Solution:

From the experimental obtained periodic course of the output variable $y(t)$ the amplitude a_y and period T_y were obtained (Fig. 4). On the basis of the relations (6b), (6c), (8), (9), (11b), (11c) and (23) for $a = a_M = a_y$ and $\omega = \omega_M$ can be obtained the relations (18), which are the same like in the example 2.2.

Example 3.2

On the basis of the relay method without hysteresis and with the integrator behind the relay for the second order oscillatory plant

$$G_P(s) = \frac{k_1}{T_0^2 s^2 + 2\xi_0 T_0 s + 1} \quad (24)$$

it is necessary to determine the plant time constant T_0 and plant damping coefficient ξ_0 on condition that the plant gain k_1 is known.

Solution:

For the plant (24) holds

$$G_P(j\omega) = A_P(\omega) e^{j\varphi_P(\omega)} \quad (25a)$$

$$A_P(\omega) = \frac{k_1}{\sqrt{(1 - \omega^2 T_0^2)^2 + 4\xi_0^2 \omega^2 T_0^2}} \quad (25b)$$

$$\varphi_P(\omega) = \begin{cases} -\arctg \frac{2\xi_0 \omega T_0}{1 - \omega^2 T_0^2} & \text{for } 0 \leq \omega < \frac{1}{T_0} \\ -\frac{\pi}{2} & \text{for } \omega = \frac{1}{T_0} \\ -\pi + \arctg \frac{2\xi_0 \omega T_0}{\omega^2 T_0^2 - 1} & \text{for } \omega > \frac{1}{T_0} \end{cases} \quad (25c)$$

For the relay without hysteresis with the integrator the relation

$$\omega_M = \omega_{-\pi/2} = \frac{1}{T_0} \Rightarrow T_0 = \frac{T_y}{2\pi} \quad (26a)$$

holds.

On the basis of the relations (6b), (25b), (26a) and the first equation in (23) can be obtained

$$\xi_0 = \frac{k_1 T_y u_0}{\pi^2 a_y} \quad (26b)$$

From the experimental obtained values a_y and T_y (see Fig. 4) by means of (26) the unknown parameters T_0 and ξ_0 can be determined.

b) Integrator is in front of relay

In this case for $w(t) = 0$ the input relay variable is given

$$\int e(t) dt = -\int a_y \sin(\omega_M t + \varphi) dt = \frac{a_y}{\omega_M} \cos(\omega_M t + \varphi) \quad (27)$$

and therefore the relation

$$a_M = \frac{a_y}{\omega_M} = \frac{a_y T_y}{2\pi} \quad (28)$$

holds.

With respect to high frequency damping by the integrator, an accuracy of the relay method with the integrator in front of the relay is less then the accuracy of the relay method with the integrator behind the relay.

Example 3.3

For proportional plant (10) from example 2.1 it is necessary by the relay method with the integrator in front of the relay to determine plant time constant T_i and plant time delay T_{di} on condition that the plant gain k_1 and plant order i are known.

Solution:

On the basis of the relations (6b), (6c), (9), (11b), (11c), (23) and (28) for $a = a_M$ and $\omega = \omega_M$ can be obtained

$$T_i = \frac{T_y}{2\pi} \sqrt[i]{\frac{16k_1^2 u_0^2}{\pi^2 a_y^2} - 1} \quad (29a)$$

$$T_{di} = \frac{T_y}{2\pi} \left(\frac{\pi}{2} - i \operatorname{arctg} \frac{2\pi T_i}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{\frac{a_y^2 T_y^2}{4\pi^2} - \varepsilon^2}} \right) \quad (29b)$$

The formula (29a) is the same as the formula (12a).

E.g. for proportional plant (13a) on the basis of the formulas (29) for $i = 1$ can be obtained

$$T_{d1} = \frac{T_y}{2\pi} \left(\frac{\pi}{2} - \operatorname{arctg} \frac{2\pi T_1}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{\frac{a_y^2 T_y^2}{4\pi^2} - \varepsilon^2}} \right) \quad (30)$$

The formula for T_1 is the same as the formula (13b).

Likewise for proportional plant with the transfer function (14a) on the basis of the formulas (29) for $i = 2$ can be obtained

$$T_{d2} = \frac{T_y}{2\pi} \left(\frac{\pi}{2} - 2 \operatorname{arctg} \frac{2\pi T_2}{T_y} - \operatorname{arctg} \frac{\varepsilon}{\sqrt{\frac{a_y^2 T_y^2}{4\pi^2} - \varepsilon^2}} \right) \quad (31)$$

The formula for T_2 is the same as the formula (14b).

Example 3.4

On the basis of the relay method without hysteresis and with the integrator in front of the relay for the second order oscillatory plant (24) from the example 3.2 it is necessary to determine the plant time constant T_0 and plant damping coefficient ξ_0 on condition that the plant gain k_1 is known.

Solution:

Likewise in the example 3.2 for the relay without hysteresis with the integrator (in front of or behind the relay) (26a) holds. Further on the basis of the relations (6b), (25b), (26a), (28) and the first equation in (23) can be obtained

$$\xi_0 = \frac{2k_1 u_0}{\pi a_y} \quad (32)$$

From the periodic course of the output variable $y(t)$ the amplitude a_y and period T_y of the oscillation and on the basis of the formulas (26a) and (32) parameters T_0 and ξ_0 can be determined.

Notice:

The plant transfer function (24) can be expressed in terms of the damping coefficient value ξ_0 in forms

$$G_p(s) = \begin{cases} \frac{k_1}{T_0^2 s^2 + 2\xi_0 T_0 s + 1} & \text{for } 0 < \xi_0 < 1 \end{cases} \quad (33a)$$

$$G_p(s) = \begin{cases} \frac{k_1}{(T_0 s + 1)^2} & \text{for } \xi_0 = 1 \end{cases} \quad (33b)$$

$$G_p(s) = \begin{cases} \frac{k_1}{(T_1 s + 1)(T_2 s + 1)} & \text{for } \xi_0 > 1 \end{cases} \quad (33c)$$

where $T_1 > T_2$ are the different plant time constants, which can be determined on the basis of the formulas

$$T_1 = T_0 \left(\xi_0 + \sqrt{\xi_0^2 - 1} \right), \quad T_2 = T_0 \left(\xi_0 - \sqrt{\xi_0^2 - 1} \right) \quad (34)$$

The plant parameters T_0 and ξ_0 can be also determined by means of the integral controller with the transfer function $1/T_i s$, which is plugged into the closed-loop system in Fig. 1 in lieu of the relay or the proportional controller with the transfer function k_p , which is plugged into the closed-loop systems in Fig. 5 in lieu of the relay and causing the stable oscillation. Then from the measured ultimate period T_c any closed-loop system variable and from the ultimate controller gain k_{pc} or the ultimate integral time $T_{ic} = 1/k_{pc}$ the above mentioned parameters can be determined on the basis of the formulas

$$T_0 = \frac{T_c}{2\pi} \quad (35a)$$

$$\xi_0 = \frac{k_1 k_{pc} T_c}{4\pi} = \frac{k_1 T_c}{4\pi T_{ic}} \quad (35b)$$

Likewise in the cases of the plants (10) and (16) the values of the ultimate parameters T_c , k_{pc} or T_{ic} must be determined iteratively but on the other side the formulas (35) are exact.

4. Conclusions

The book chapter describes the use of the relay method with and without hysteresis and further more with and without integrator, which is plugged in behind or in front of the relay for experimental identification of the simple plants. The relay method without the integrator is suitable for proportional and integral plants and the relay method with the integrator is suitable only for proportional plants. For proportional and integral plants with multiple time constants with time delay and for second order oscillatory proportional plant the general formulas for computation of their two parameters are derived. Experimentally it is possible to obtain one point of the plant frequency response, i.e. two values of the plant

parameters, it is possible by means of several experiments (with or without hysteresis, without or with the integrator, with the integrator in front of or behind the relay) to obtain more values of the plant parameters or take out the average of these values etc. It is obvious that the relay methods can be used only for the plants, which can oscillate or which cannot be destroyed by oscillation.

This work was supported by research project GACR No 102/09/0894.

5. References

- Åström, K. (1993). Autonomous Controllers. *Control Engineering Practice*, Vol. 1, No. 2, 1993, pp. 227-232
- Åström, K. & Hägglund, T. (1995). *PID Controllers: Theory, Design, and Tuning*. 2nd Edition, Instrument Society of America, ISBN 1-55617-516-7, Research Triangle Park, North Carolina
- Åström, K. & Wittenmark, B. (1989). *Adaptive Control*. Addison-Wesley, ISBN 0201558661, Massachusetts
- Besançon-Voda, A. & Roux-Buisson, H. (1997). Another Version of the Relay Feedback Experiment. *Journal of Process Control*, Vol. 7, No. 4, 1997, pp. 303-308
- Bi, Q. Wang, Q. G. & Hang, C.C. (1997). Relay-based Estimation of Multiple Points on Process Frequency Response. *Automatica*, Vol. 33, No. 9, 1997, pp. 1753-1757
- Halevi, Y. Palmor, Z. J. & Efrati, T. (1997). Automatic Tuning of Decentralized PID Controllers for MIMO Processes. *Journal of Process Control*, Vol. 7, No. 2, 1997, pp. 119-128
- Hang, C. C., Lee, H. T. & Ho, W. K. (1993). *Adaptive Control*. Instrument Society of America, ISBN 1-55617-477-2, Research Triangle Park, North Carolina
- Hang, C. C., Åström, K. J. & Wang, Q. G. (2002). Relay Feedback Auto-tuning of Process Controllers – a Tutorial Review. *Journal of Process Control*, No. 12, 2002, pp. 143-162
- Huang, H. P., Jeng, J. C. & Luo, K. Y. (2005). Auto-tune System Using Single-run Relay Feedback Test and Model-based Controller Design. *Journal of Process Control*, 15, 2005, pp. 713-727
- Johnson, M. A. & Moradi, M. H. (2005). *PID Control. New Identification and Design Methods*. Springer-Verlag, ISBN 1-85233-702-8, London
- Kaya, I. & Atherton, D. P. (2001). Parameter Estimation from Relay Autotuning with Asymmetric Limit Cycle Data. *Journal of Process Control*, No. 11, 2001, pp. 429-439
- Lee, T. H., Wang, Q. G. & Tann, K. K. (1995). Knowledge-based Process Identification from Relay Feedback. *Journal of Process Control*, Vol. 5, No. 6, 1995, pp. 387-397
- Leva, A. & Donida, F. (2009). Autotuning in Cascaded Systems Based on a Single Relay Experiment. *Journal of Process Control*, 19, 2009, pp. 896-905
- Leva, A. & Maggio, M. (2009). The PI+p Controller Structure and Its Tuning. *Journal of Process Control*, (article in press), doi:10.1016/j.jprocont.2009.05.007
- Liu, T. & Gao, F. (2009). A Generalized Relay Identification Method for Time Delay and Non-minimum Phase Processes. *Automatica*, 45, 2009, pp. 1072-1079
- Loh, A. P. & Vasnani, V. U. (1994). Describing Function Matrix for Multivariable Systems and Its Use in Multiloop PI Design. *Journal of Process Control*, Vol. 4, No. 3, 1994, pp. 115-120

- Luo, R., Qin, S. J. & Chen, D. (1998). A New Approach to Closed-Loop Autotuning for Proportional-Integral-Derivative Controllers. *Ind. Eng. Chem. Res.*, 37, pp. 2462-2468
- Majhi, S. (2005). On-line PI Control of Stable Processes. *Journal of Process Control*, 15, 2005, pp. 859-867
- Majhi, S. (2007). Relay Based Identification of Processes with Time Delay. *Journal of Process Control*, 17, 2007, pp. 93-101
- Panda, R. C. & Yu, C. C. (2003). Analytical Expressions for Relay Feedback Responses. *Journal of Process Control*, 13, 2003, pp. 489-501
- Panda, R. C. & Yu, C. C. (2005). Shape Factor of Relay Response Curves and Its Use in Autotuning. *Journal of Process Control*, 15, 2005, pp. 893-906
- Prokop, R., Pekař, L. & Korbel, J. (2010). Autotuning for Delay Systems Using Meromorphic Functions. In *Proceedings of the 9th IFAC Workshop on Time Delay Systems* (6 p. on CD), Prague, Czech Republic, June 7-9, 2010
- Rotač, V. Ja. (1964). *Design and Tuning of Industrial Control Systems (in Czech)*. SNTL, Prague
- Semino, D. & Scali, C. (1998). Improved Identification and Autotuning of PI Controllers for MIMO Processes by Relay Techniques. *Journal of Process Control*, Vol. 8, No. 3, 1998, pp. 219-227
- Shen, S. H., Yu, H. D. & Yu, C. C. (1999). Autotune Identification for System with Right-half-plane Poles and Zeros. *Journal of Process Control*, 9, 1999, pp. 161-169
- Sung, S. W., Lee, J. & Lee, I. (2009). *Process Identification and PID Control*. John Wiley & Sons, ISBN 978-0-470-82410-8, Singapore
- Tan, K. K., Lee, T. H. & Jiang, X. (2001). On-line Relay Identification, Assessment and Tuning of PID Controller. *Journal of Process Control*, No. 11, 2001, pp. 483-496
- Tan, K. K., Huang, S. & Ferdous, R. (2002). Robust Self-tuning PID Controller for Nonlinear Systems. *Journal of Process Control*, 12, 2002, pp. 753-761
- Tan, K. K., Lee, T. H., Chua, K. Y. & Ferdous, R. (2006). Improved Critical Point Estimation Using a Preload Relay. *Journal of Process Control*, 16, 2006, pp. 445-455
- Tan, K. K., Lee, T. H. & Wang, Q. G. (1996). Enhanced Automatic Tuning Procedure for Process Control of PI/PID Controllers. *AIChE Journal*, Vol. 42, No. 9, 1996, pp. 2555-2562
- Vítečková, M. & Víteček, A. (2005). Experimental Plant Identification by Relay Method. *Transactions of the VŠB – Technical University of Ostrava, Mechanical Series*, Vol. LI, No. 2, 2005, pp. 155-166, ISSN 11210-0471
- Vivek, S. & Chidambaram, M. (2005). An Improved Relay Autotuning of PID Controllers for Unstable FOPTD Systems. *Computers and Chemical Engineering*, 29, 2005, pp. 2060-2068
- Vukić, Z., Kuljača, L., Đonlagić, D. & Tešnjak, S. (2003). *Nonlinear Control Systems*. Marcel Dekker, ISBN 0-8247-4112-9, New York
- Wang, Q. G., Hang, C. C. Zhu, S. A. & Bi, Q. (1999). Implementation and Testing of an Advanced Relay Auto-tuner. *Journal of Process Control*, 9, 1999, pp. 291-300

IntechOpen

IntechOpen

Engineering the Future

Edited by Laszlo Dudas

ISBN 978-953-307-210-4

Hard cover, 414 pages

Publisher Sciyo

Published online 02, November, 2010

Published in print edition November, 2010

This book pilots the reader into the future. The first three chapters introduce new materials and material processing methods. Then five chapters present innovative new design directions and solutions. The main section of the book contains ten chapters organized around problems and methods of manufacturing and technology, from cutting process optimisation through maintenance and control to the Digital Factory. The last two chapters deal with information and energy, as the foundations of a prospering economy.

How to reference

In order to correctly reference this scholarly work, feel free to copy and paste the following:

Antonin Vitecek and Miluše Vítěčková (2010). Plant Identification by Relay Method, Engineering the Future, Laszlo Dudas (Ed.), ISBN: 978-953-307-210-4, InTech, Available from:
<http://www.intechopen.com/books/engineering-the-future/plant-identification-by-relay-method>

INTECH
open science | open minds

InTech Europe

University Campus STeP Ri
Slavka Krautzeka 83/A
51000 Rijeka, Croatia
Phone: +385 (51) 770 447
Fax: +385 (51) 686 166
www.intechopen.com

InTech China

Unit 405, Office Block, Hotel Equatorial Shanghai
No.65, Yan An Road (West), Shanghai, 200040, China
中国上海市延安西路65号上海国际贵都大饭店办公楼405单元
Phone: +86-21-62489820
Fax: +86-21-62489821

© 2010 The Author(s). Licensee IntechOpen. This chapter is distributed under the terms of the [Creative Commons Attribution-NonCommercial-ShareAlike-3.0 License](https://creativecommons.org/licenses/by-nc-sa/3.0/), which permits use, distribution and reproduction for non-commercial purposes, provided the original is properly cited and derivative works building on this content are distributed under the same license.

IntechOpen

IntechOpen