We are IntechOpen, the world's leading publisher of Open Access books Built by scientists, for scientists



185,000

200M



Our authors are among the

TOP 1% most cited scientists





WEB OF SCIENCE

Selection of our books indexed in the Book Citation Index in Web of Science™ Core Collection (BKCI)

## Interested in publishing with us? Contact book.department@intechopen.com

Numbers displayed above are based on latest data collected. For more information visit www.intechopen.com



### **Mechanical Transmissions Parameter Modelling**

Isad Saric, Nedzad Repcic and Adil Muminovic University of Sarajevo, Faculty of Mechanical Engineering, Department of Mechanical Design, Bosnia and Herzegovina

#### 1. Introduction

In mechanical technique, transmission means appliance which is used as intermediary mechanism between driving machine (e.g. of engine) and working (consumed) machine. The role of transmission is transmitting of mechanical energy from main shaft of driving machine to main shaft of working machine. The selection of transmission is limited by the price of complete appliance, by working environment, by dimensions of the appliance, technical regulations, etc. In mechanical engineering, so as in technique generally, mechanical transmissions are broadly used. Mechanical transmissions are mechanisms which are used for mechanical energy transmitting with the change of angle speed and appropriate change of forces and rotary torques. According to the type of transmitting, mechanical transmissions could be divided into: transmissions gear (sprocket pair), belt transmissions (belt pulleys and belt), friction transmissions (friction wheels) and chain transmissions (chain pulleys and chain). (Repcic & Muminovic, 2007)

In this chapter, the results of the research of three-dimensional (3D) geometric parameter modelling of the two frequently used types of mechanical transmissions, transmissions gear (different types of standard catalogue gears: spur gears, bevel gears and worms) and belt transmissions (belt pulley with cylindrical external surface, or more exactly, with pulley rim) using CATIA V5 software system (modules: *Sketcher, Part Design, Generative Shape Design, Wireframe and Surface Design* and *Assembly Design*), is shown.

Modelling by computers are based on geometric and perspective transformation which is not more detail examined in the chapter because of their large scope.

It is advisable to make the parameterisation of mechanical transmissions for the purpose of automatization of its designing. Parameter modelling application makes possible the control of created geometry of 3D model through parameters integrated in some relations (formulas, parameter laws, tables and so on). All dimensions, or more precisely, geometric changeable parameter of gear and belt pulley, can be expressed through few characteristic fixed parameters (m, z,  $z_1$ ,  $z_2$  and N for the selected gear; d,  $B_k$ ,  $d_v$  and s for the selected belt pulley). Geometry of 3D mechanical transmission model is changed by changes of these parameters values. Designer could generate more designing solutions by mechanical transmission parameterisation.

Because AutoCAD does not support parameter modelling, and command system, that it has, does not make possible simple realization of changes on finished model, parameter

oriented software systems (CATIA V5, SolidWorks, Mechanical Desktop, and so on) which used analytical expressions for variable connection through parameters are used. CATIA V5 (Computer-Aided Three-dimensional Interactive Application) is the product of the highest technological level and represents standard in the scope of designing (Dassault Systemes, IBM, 2011). Currently, it is the most modern integrated CAD/CAM/CAE software system that can be find on the market for commercial use and scientific-research work. The biggest and well-known world companies and their subcontractors use them. It is the most spread in the car industry (Daimler Chrysler, VW, BMW, Audi, Renault, Peugeot, Citroen, etc.), airplane industry (Airbus, Boeing, etc.), and production of machinery and industry of consumer goods. The system has mathematical models and programs for graphical shapes presentation, however users have no input about this process. As a solution, it is written independently from operative computer system and it provides the possibility for program module structuring and their adaptation to a user. In the "heart" of the system is the integrated associational data structure for parameter modelling, which enables the changes on the model to be reflected through all related phases of the product development. Therefore, time needed for manual models remodelling is saved. The system makes possible all geometric objects parametering, including solids, surfaces, wireframe models and constructive elements. (Karam & Kleismit, 2004; Saric et al., 2010) Whole model, or part of model, can parameterise in the view of providing of more flexibility in the development of new variants designing solutions. Intelligent elements interdependence is given to a part or assembly by parameterising. The main characteristic of parameter modelling in CATIA V5 system is the great flexibility, because of the fact that parameters can be, but do not have to be, defined in any moment. Not only changing of parameter value, but their erasing, adding and reconnecting, too, are always possible. (Karam & Kleismit, 2004) Total Graphical User Interface (GUI) programmed in C++ program is designed like tools palette and icons that can be find in Windows interface. Although it was primarily written for Windows and Windows 64-bit, the system was written for AIX, AIX 64-bit, HP-UX, IRIX and Solaris operative system. To obtain the maximum during the work with CATIA V5 system, optimized certificated hardware configurations are recommended (Certified hardware configurations for CATIA V5 systems, 2011).

Parameter modelling in CATIA V5 system is based on the concept of knowledge, creating and use of parameter modelled parts and assemblies. (Saric et al., 2009) Creating of 3D parameter solid models is the most frequently realized by combining of the approach based on *Features Based Design* – FBD and the approach based on Bool's operations (*Constructive Solid Geometry* – CSG). (Amirouche, 2004; Shigley et al. 2004; Spotts at el., 2004) The most frequent parameter types in modelling are: *Real, Integer, String, Length, Angle, Mass*, etc. They are devided into two types:

- internal parameters which are generated during geometry creating and which define its interior features (depth, distance, activity, etc.) and
- user parameters (with one fixed or complex variables) which user specially created and which define additional information on the: *Assembly Level, Part Level* or *Feature Level*.

So, parameter is a variable we use to control geometry of component, we influence its value through set relations. It is possible to do a control of geometry by use of tools palette *Knowledge* in different ways:

4

- by creating of user parameters set and by their values changing,
- by use of defined formulas and parameter laws that join parameters,
- by joining of parameters in designed tables and by selection of appropriate configured set.

The recommendation is, before components parameterising, to:

- 1. check the component complexity,
- 2. notice possible ways of component making,
- 3. notice dimensions which are going to change and
- 4. select the best way for component parameterising.

#### 2. Mechanical transmissions parameter modelling

Modelling of selected mechanical transmissions was done in *Sketcher, Part Design* and *Generative Shape Design* modules of CATIA V5 system. As prerequisite for this way of modelling, it is necessary to know modelling methodology in modules *Wireframe and Surface Design* and *Assembly Design* of CATIA V5 system. (Karam & Kleismit, 2004; Dassault Systemes, 2007a, 2007b; Zamani & Weaver, 2007)

After finished modelling procedure, mechanical transmissions can be independently used in assemblies in complex way.

Parameter marks and conventional formulas (Table 1. and 5.) used in mechanical transmissions modelling can be found in references (Repcic & et al., 1998; Repcic & Muminovic, 2007, pgs. 139, 154-155, 160-161). Clear explanations for transmissions gear and belt transmissions can be found in references (Repcic & et al., 1998, pgs. 54-106, 118-151).

#### 2.1 Transmissions gear parameter modelling

Next paragraph is shows 3D geometric parameter modelling of characteristic standard catalogue gears: spur gears, bevel gears and worms.

Gears were selected as characteristic example, either because of their frequency as mechanical elements or because exceptionally complex geometry of cog side for modelling.

Every user of software system for designing is interested in creation of complex plane curve *Spline* which defined geometry of cog side profile.

The control of 3D parameterised model geometry is done by created parameters, formulas and parameter laws shown in the tree in Fig. 1. (Cozzens, 2006) Parameters review, formulas and parameter laws in the *Part* documents tree activating is done through the main select menu (*Tools*  $\rightarrow$  *Options*  $\rightarrow$  *Part Infrastructure*  $\rightarrow$  *Display*).

Spur gear	Bevel gear	Worm
Z	z1, z2	z1=1
т		<i>m</i> =1,5
<i>a</i> =20 deg		
p=m*PI		
$r = (z^*m)/2$	$r=(z1^{*}m)/2$	<i>d</i> =20 mm
$rb=r^*\cos(a)$	$rb=rc^*\cos(a)$	

Spur gear	Bevel gear	Worm
rf=r-1.2*m		
ra=r+m		ra=d/2+ha
rr=0.38*m	· · · ·	· · · · ·
ha=m		
hf=1.2*m		
$xd = rb^*(\cos(t^*PI) - t)$	+sin( <i>t*PI</i> )* <i>t*PI</i> )	N=6,5
$yd=rb^*(\sin(t^*PI)-$	cos( <i>t</i> * <i>PI</i> )* <i>t</i> * <i>PI</i> )	L=(N+1)*p
0≤ <i>t</i> ≤1		gama=atan(m*z1/d)
	delta=atan(z1/z2)	dZ=-L/2
	$rc=r/\cos(delta)$	
	$lc=rc/\sin(delta)$	
	tc=-atan(Relations\yd.Evaluate(a/	′180deg)/
	Relations\xd.Evaluate(a/180deg))	)
	b=0.3*rc	
	$ratio=1-b/lc/\cos(delta)$	
	dZ=0  mm	

Table 1. Parameters and formulas




Fig. 1. Gear geometry control

#### 2.1.1 Spur gears parameter modelling

To define fixed parameters (Fig. 2.), we select command *Formula* for from tools palette *Knowledge* or from main select menu. Then, we:

- 1. choose desired parameter type (*Real, Integer, Length, Angle*) and press the button *New Parameter of type,*
- 2. type in a new parameter name,
- 3. assign a parameter value (only in the case if parameter has fixed value) and
- 4. press the button *Apply* to confirm a new parameter creation.

			Import
ter On Spur_Gear			
ter Name :			
ter Type : User parameters	-		
tor type t jusci parameters			
uble click on a parameter to edit it			
and a parameter to cak k	Value	Formula	Active
	20		111111
	2mm		
	20deg		
	6,283r		yes
	20mm	= (z*m)/2	yes
0	18,794		yes
	17,6m	m = r - 1.2 * m	yes
it name or value of the current param	eter		
$\left( 2 \right)$		2mm (3)	3
			4
	and the second sec		
New Parameter of type Real 1	With Single Value		Add Formula

Fig. 2. Fixed parameters defining

- 6E			Impo	rt
Filter On Spur_Gear				
Filter Name :				
Filter Type : User parameters	•			
Double click on a parameter to edit it				
Parameter	Value	Formula	Active	^
2	20			
m	2mm			
a	20deg 6,283mm	= m * PI	yes	
F	20mm	$= (z^* m)/2$	yes	
rb	18,794mm	$= r^* \cos(a)$	yes	-
rf	17,6mm	= r - 1.2 * m	yes	$\sim$
Edit name or value of the current parameter				
r (2)	2	Omai 🗧	1	
	and least of the			- 14 C
New Parameter of type Real (1)	✓ With Single Value	<b>_</b>	3 Add Form	ula

Fig. 3. Changeable parameters defining

Most geometrical gear parameters are changeable and are in the function of fixed parameters m and z (Fig. 3.). We do not need to set values for these parameters, because CATIA V5 system calculates them itself. So, instead of values setting, formulas are defined by choosing the command Formula  $f_{\Theta}$  (Fig. 4.). When formula has been created, it is possible to manipulate with it by the tree, similar as with any other model feature.

r					
(z*m)/2					
Dictionary		Members of Parameters		Members of All	
Parameters Design Table Operators Pointer on value functions Point Constructors Law Line Constructors		All Renamed parameters Boolean CstAttr_Mode Length Angle Plane		PartBody\Sketch.1\Activity PartBody\Sketch.1\AbsoluteAxis\Activity PartBody\Sketch.1\Doincidence.19\Activity PartBody\Sketch.1\Coincidence.19\mode PartBody\Sketch.1\Parallelism.20\Activity PartBody\Sketch.1\Parallelism.21\Activity	
Circle Constructors	~	Integer	*	<	>

Fig. 4. Formula setting

/*Law created by Isad Saric 17 xd = rb * ( cos( t * PI * 1rad )		PI)	Formal parameters Type
			xd Length t t New Parameter of type Real
ictionary N	Members of Parameters	Members of All	Remove
Parameters Keywords Design Table Operators Pointer on value function Point Constructors	All Renamed parameters Boolean CstAttr_Mode Length Angle Plane Integer	PartBody/Sketch.1\Activity PartBody/Sketch.1\Activity PartBody/Sketch.1\Coincidence.19\Activity PartBody/Sketch.1\Coincidence.19\mode PartBody/Sketch.1\Parallelism.20\Activity PartBody/Sketch.1\Parallelism.20\Activity PartBody/Sketch.1\Parallelism.21\Activity PartBody/Sketch.1\Parallelism.21\mode	

Fig. 5. Setting of parameter laws for calculation of x and y coordinates of involute points

Position of the points on involutes profile of cog side is defined in the form of parameter laws (Fig. 5.). For coordinate points of involute (x0,y0), (x1,y1), ...., (x4,y4) we most frequently define a set of parameters. To create parameter laws, we choose the command Law fog from tools palette *Knowledge*. Then, we give two laws in parameter form, which we are going to be used for calculation of *x* and *y* coordinate points of involute

$$xd = rb^* (\cos(t^* PI^* 1 rad) + \sin(t^* PI^* 1 rad)^* t^* PI)$$
(1)

8

$$yd = rb^{*}(\sin(t^{*}PI^{*}1rad) - \cos(t^{*}PI^{*}1rad)^{*}t^{*}PI)$$
(2)

While we use law editor, we have to take into account the following:

- trigonometric functions, specially angles, are not considered as numbers, and because of that angle constants like 1*rad* or 1deg must be used,
- *PI* is the value of the number  $\pi$ .

For the purpose of accuracy checking of previously conducted activities, review of formulas, parameter laws and values of all defined fixed and changeable parameters is activated in the tree of *Part* document (*Tools*  $\rightarrow$  *Options*  $\rightarrow$  *Knowledge*).

The example of spur gear parameter modelling is shown in the next paragraph. All dimensions, or more precisely, geometric changeable parameters of spur gear are in the function of fixed parameters m and z. We can generate any spur gear by changing parameters m and z.

Part Number	т	Z	$d_g$	d	$b_z$	$b_g$	$b_k$	$t_k$
G2-20	2	20	30	15	20	35	5	2,35
G3-40	3	40	60	25	30	50	8	3,34
G4-60	4	60	120	30	40	60	10	3,34

Table 2. Selected spur gears parameters




Fig. 6. Different spur gears are the result of parameter modelling

Fig. 6. shows three different standard catalogue spur gears made from the same CATIA V5 file, by changing parameters *m* and *z*. (Saric et al., 2009, 2010)

#### 2.1.2 Bevel gears parameter modelling

The example of bevel gear parameter modelling is shown in the next paragraph. All dimensions, or more precisely, geometric changeable parameters of bevel gear are in the function of fixed parameters m,  $z_1$  and  $z_2$ . We can generate any bevel gear by changing parameters m,  $z_1$  and  $z_2$ .

Part Number	т	$z_1$	<i>z</i> <sub>2</sub>	dg	d	$b_z$	bg	Connection between hub and shaft
B2-25	2	25	25	40	12	10,6	25,52	M5
DB3-15	3	15	30	36	18	17	36,26	M6
FB4-15	4	15	60	48	20	34	59,9	M8

Table 3. Selected bevel gears parameters

Fig. 7. shows three different standard catalogue bevel gears made from the same CATIA V5 file, by changing parameters m,  $z_1$  and  $z_2$ . (Saric et al., 2009, 2010)




Fig. 7. Different bevel gears are the result of parameter modelling

#### 2.1.3 Worms parameter modelling

The example of worm parameter modelling is shown in the next paragraph. All dimensions, or more precisely, geometric changeable parameters of worm are in the function of fixed parameters m,  $z_1$  and N. We can generate any worm by changing parameters m,  $z_1$  and N.

Part Number	т	$z_1$	$d_g$	d	L	Lg	Connection between hub and shaft
W1,5-1	1,5	1	23	10	35	45	M5
W2,5-2	2,5	2	35	15	45	60	M6
-W3-3	_3	3	41	20	55	70	M8

Table 4. Selected worms parameters



Fig. 8. Different worms are the result of parameter modelling

Fig. 8. shows three different standard catalogue worms made from the same CATIA V5 file, by changing parameters *m*, *z*<sub>1</sub> and *N*. (Saric et al., 2009, 2010)

#### 2.2 Belt transmissions parameter modelling

This application includes wide area of the industry for the fact that belt transmitting is often required. Generally, belt transmitting designing process consists of needed drive power estimate, choice of belt pulley, length and width of belt, factor of safety, etc. Final design quality can be estimated by efficiency, compactness and possibilities of service. If engineer does not use parameter modelling, he/she must pass through exhausting phase of design, based on learning from the previous done mistakes, in order to have standard parts like belt pulleys and belts, mounted on preferred construction. This process is automatized by parameter modelling. In such process, characteristics that registered distance between belt pulleys, belts length, etc., are also created. Such characteristics, also, register links, belt angle speeds and exit angle speed. The results for given belts length can be obtained by the feasibility study. Few independent feasibility studies for the different belts lengths are compared with demands for compactness. In such a way, several constructions of belt transmitting can be tested, and then it is possible to find the best final construction solution.

The example of belt pulley parameter modelling is shown in the next paragraph. The belt pulley *K* is shown in the Fig. 9., and it consists of several mutual welded components: hub *G*, pulley rim *V*, plate *P* and twelve side ribs *BR*. All dimensions, or more precisely, geometric changeable parameters of belt pulley are in function of fixed parameters *d*,  $B_k$ ,  $d_v$  and *s*. We can generate any belt pulley with cylindrical external surface by changing parameters *d*,  $B_k$ ,  $d_v$  and *s*.




Fig. 9. Modelling of belt pulley parts with cylindrical external surface

Dimensions of hub depends from diameter of shaft  $d_v$ , on which hub is set. Shaft diameter is the input value through which the other hub dimension are expressed.

Hub shape can be obtained by adding and subtraction of cylinders and cones shown in the Fig. 9.

(5)

$$G = CYL1 + CYL2 - CYL3 - KON1 - KON2 - KON3 - KON4$$

$$(3)$$

Pulley rim of belt pulley depends from diameter of belt pulley d, pulley rim width  $B_k$ , diameter of shaft  $d_v$  and minimal pulley rim thickness s.

$$V = CYL4 - CYL5 - CYL6 - KON5 - KON6$$
<sup>(4)</sup>

Plate dimensions depend from diameter of belt pulley d, minimal pulley rim thickness s and diameter of shaft  $d_v$ .

Side ribs are side set rectangular plates which can be shown by primitive in the form of prism.

 $P = CYL7 - CYL8 - 6 \cdot CYL9$ 

$$BR = BOX \tag{6}$$

Whole belt pulley is obtained by adding of formed forms.

$$K = G + V + P + 6 \cdot BR \tag{7}$$

Belt pulley with cylin	drical external surface
CYL1: D=1,6 ·d <sub>v</sub> , H=0,75 ·d <sub>v</sub>	<i>CYL9</i> : <i>H</i> = 0,1 $d_v$
<i>CYL2</i> : <i>D</i> =1,7 · <i>d</i> <sub>v</sub> , <i>H</i> =0,65 · <i>d</i> <sub>v</sub> +2 mm	<i>KON</i> 1: <i>D</i> =1,6 <i>d</i> <sub>v</sub> , <i>H</i> =1 mm, angle 45°
CYL3: $D=d_v$ , $H=1,4 \cdot d_v+2 \text{ mm}$	<i>KON</i> 2: <i>D</i> =1,7 <i>d<sub>v</sub></i> , <i>H</i> =1 mm, angle 45°
$CYL4: D=d, H=B_k$	KON3: $D=d_v$ , $H=1$ mm, angle $45^{\circ}$
CYL5: $D=d-2$ s, $H=B_k/2+0.05 d_v+1$ mm	KON4: $D=d_v$ , $H=1$ mm, angle 45°
CYL6: $D=d-2$ s-0,1 $d_v$ , $H=B_k/2-0,05$ $d_v-1$ mm	<i>KON5</i> : <i>D</i> = <i>d</i> -2 <i>s</i> -0,1 <i>d<sub>v</sub></i> , <i>H</i> =1 mm, angle 45°
<i>CYL7</i> : <i>D</i> = <i>d</i> -2 · <i>s</i> , <i>H</i> =0,1 · <i>d</i> <sub>v</sub>	<i>KON</i> 6: <i>D</i> = <i>d</i> -2 <i>s</i> , <i>H</i> =1 mm, angle 45°
CYL8: D=1,6 ·d <sub>v</sub> , H=0,1 ·d <sub>v</sub>	BOX: $A = [(d-2 \cdot s)-1, 8 \cdot d_v]/2, B=0,35 \cdot B_k, C=0,1 \cdot d_v$

Table 5. Parameters and formulas



Fig. 10. Different belt pulleys with cylindrical external surface are the results of parameter modelling

Fig. 10. shows three different standard belt pulleys with cylindrical external surface made from the same CATIA V5 file, by changing parameters d,  $B_k$ ,  $d_v$  and s. (Saric et al., 2009)

Use of side ribs that are posed between holes on the plate is recommended during modelling of belt pulleys with longer diameter (Fig. 10.).

Rotary parts of belt pulley shown in the Fig. 9., can be modelled in a much more easier way. More complex contours, instead of their forming by adding and subtraction, they can be formed by rotation. In the first case, computer is loaded with data about points inside primitive which, in total sum, do not belong inside volume of component. In the second case, rotary contour (bolded line in the Fig. 11.) is first defined, and, then, primitive of desired shape is obtained by rotation around rotate axis.




Fig. 11. Modelling of rotary forms

For primitives, shown in the Fig. 11., final form is obtained after the following operations

$$K = (ROT1 - ROT2 - 6 \cdot CYL) \cup 6 \cdot BOX$$
(8)

#### 3. Conclusion

Designer must be significantly engaged into the forming of the component shape. Because of that reason, once formed algorithm for the modelling of the component shape is saved in computer memory and it is used when there is need for the modelling of the same or similar shape with similar dimensions. (Saric et al., 2009)

Parts which are not suitable for interactive modelling are modelled by parameters. In the process of geometric mechanical transmission modelling in CATIA V5 system, we do not have to create shape directly, but, instead of that, we can put parameters integrated in geometric and/or dimensional constraints. Changing of characteristic fixed parameters gives us a 3D solid model of mechanical transmission. This way, designer can generate more alternative designing samples, concentrating his attention on design functional aspects, without special focus on details of elements shape. (Saric et al., 2010)

For the purpose of final goal achieving and faster presentation of the product on the market, time spent for the development of the product is marked as the key factor for more profit gaining. Time spent for process of mechanical transmissions designing can be reduced even by 50% by parameter modelling use with focus on the preparatory phase (Fig. 12.).




Fig. 12. Relation of design activities and reducing of time spent for design by parameter modelling

These are the advantages of parameter modelling use:

- possibility to make family of parts with the same shape based on one created model,
- forming of libraries basis of standard mechanical elements which take up computer memory, similar to the classic approach of 3D geometric modelling, is not necessary,
- use of parameters enables global modification of whole assembly (automatic reconfiguration),
- development of the product is faster, etc. (Saric et al., 2009)

We can conclude that CATIA V5 system offers possibility of geometric association creation defined by relations established between parameters. Therefore, components parameterisation must obligatory apply in combination with today's traditional geometric modelling approach. Direct financial effects can be seen in production costs reduction, which increases the productivity. Therefore profit is bigger and price of products are lower. (Saric et al., 2010)

Obtained 3D model from CATIA V5 system is used as the base for technical documentation making, analysis of stress and deformation by *Finite Element Method* (FEM), generating of NC/CNC programs for production of the parts on machine (CAM/NC), *Rapid Prototyping* (RP), etc.

#### 4. Acknowledgment

Researches were partially financed by WUS Austria under supervision of Austrian Ministry of foreign affairs as the part of CDP+ project (No. project: 43-SA-04).

14

#### 5. Nomenclature

А	mm	side rib length						
а	0	line of contact angle						
В	mm	side rib width						
$B_k$	mm	pulley rim width						
BR	-	side rib						
b	mm	cog width						
bg	mm	hub width						
$b_k$	mm	keyway width						
bz	mm	gear width						
С	mm	side rib thickness						
CYL	-	cylinder						
D	mm	appropriate diameter of belt pulley components						
d	mm	gear pitch circle; diameter of the hole for shaft; diameter of belt pulley						
dg	mm	interior diameter of hub						
do	mm	diameter of the hole on the plate						
d <sub>op</sub>	mm	diameter on which holes on plate are set						
$d_v$	mm	diameter of shaft						
delta	0	a half of an angle of front cone						
dZ	mm	translation of geometry over z axis; translation of worm surface over z axis						
G	-	hub						
gama	0	angle of helix						
Н	mm	appropriate length of belt pulley components						
ha	mm	addendum part of cog height						
hf	mm	root part of cog height						
Κ	-	belt pulley						
KON	-	cone						
L	mm	helix length						
Lg	mm	hub length						
lc	mm	cone axis length						
m	mm	module						
Ν	-	number of helix						
Р	-	plate						
PI		value of number $\pi$						
р	mm	step on pitch circle						
ROT	-	rotation						
r	mm	pitch radius						
ra	mm	addendum radius						
ratio	-	factor of scaling exterior to interior cog profile						
rb	mm	basic radius						
rc	mm	length of generating line of back (additional) cone						
rf	mm	root radius						
rr	mm	radius of profile root radius						
S	mm	minimal pulley rim thickness						

t	-	involutes function parameter
t <sub>k</sub>	mm	keyway depth
tc	0	cutting angle used for contact point putting in zx plane
V	-	pulley rim
xd	mm	x coordinate of involutes cog profile generated on the base of parameter t
yd	mm	y coordinate of involutes cog profile generated on the base of parameter t
(x,y)	mm	coordinates of involute points
z	) I	cog number
Z1	( - )	cog number of driver gear; number of turn of a worm
Z2	-	cog number of following gear

#### 6. References


- Amirouche, F. (2004). *Principles of Computer-Aided Design and Manufacturing* (2nd edition), Prentice Hall, ISBN 0-13-064631-8, Upper Saddle River, New Jersey
- Certified hardware configurations for CATIA V5 systems. (May 2011). Available from: <a href="http://www.3ds.com/support/certified-hardware/overview/">http://www.3ds.com/support/certified-hardware/overview/</a>
- Cozzens, R. (2006). Advanced CATIA V5 Workbook: Knowledgeware and Workbenches Release 16. Schroff Development Corporation (SDC Publications), ISBN 978-1-58503-321-8, Southern Utah University

Dassault Systemes. (2007a). CATIA Solutions Version V5 Release 18 English Documentation

- Dassault Systemes. (2007b). CATIA Web-based Learning Solutions Version V5 Release 18 Windows
- Dassault Systemes PLM solutions, 3D CAD and simulation software. (May 2011). Available from: <a href="http://www.3ds.com/home/">http://www.3ds.com/home/</a>>

International Business Machines Corp. (IBM). (May 2011). Available from: <a href="http://www.ibm.com/us/en/">http://www.ibm.com/us/en/</a>

- Karam, F. & Kleismit, C. (2004). Using Catia V5, Computer library, ISBN 86-7310-307-X, Cacak
- Repcic, N. et al. (1998). *Mechanical Elements II Part*, Svjetlost, ISBN 9958-10-157-7 (ISBN 9958-11-075-X), Sarajevo
- Repcic, N. & Muminovic, A. (2007). *Mechanical Elements II*, Faculty of Mechanical Engineering, Sarajevo
- Saric, I., Repcic, N. & Muminovic, A. (2006). 3D Geometric parameter modelling of belt transmissions and transmissions gear. *Technics Technologies Education Management – TTEM*, Vol. 4, No. 2, (2009), pp. 181-188, ISSN 1840-1503
- Saric, I., Repcic, N. & Muminovic, A. (1996). Parameter Modelling of Gears, Proceedings of the 14th International Research/Expert Conference "Trends in the Development of Machinery and Associated Technology – TMT 2010", pp. 557-560, ISSN 1840-4944, Mediterranean Cruise, September 11-18, 2010
- Shigley, J.E., Mischke, C.R. & Budynas, R.G. (2004). *Mechanical Engineering Design* (7th edition), McGraw-Hill, ISBN 007-252036-1, New York
- Spotts, M.F., Shoup, T.E. & Hornberger, L.E. (2004). *Design of Machine Elements* (8th edition), Prentice Hall, ISBN 0-13-126955-0, Upper Saddle River, New Jersey
- Zamani, N.G. & Weaver, J.M. (2007). *Catia V5: Tutorials Mechanism Design & Animation*, Computer library, ISBN 978-86-7310-381-5, Cacak



Mechanical Engineering Edited by Dr. Murat Gokcek

ISBN 978-953-51-0505-3 Hard cover, 670 pages **Publisher** InTech **Published online** 11, April, 2012 **Published in print edition** April, 2012

The book substantially offers the latest progresses about the important topics of the "Mechanical Engineering" to readers. It includes twenty-eight excellent studies prepared using state-of-art methodologies by professional researchers from different countries. The sections in the book comprise of the following titles: power transmission system, manufacturing processes and system analysis, thermo-fluid systems, simulations and computer applications, and new approaches in mechanical engineering education and organization systems.

#### How to reference

In order to correctly reference this scholarly work, feel free to copy and paste the following:

Isad Saric, Nedzad Repcic and Adil Muminovic (2012). Mechanical Transmissions Parameter Modelling, Mechanical Engineering, Dr. Murat Gokcek (Ed.), ISBN: 978-953-51-0505-3, InTech, Available from: http://www.intechopen.com/books/mechanical-engineering/mechanical-transmissions-parameter-modelling



#### InTech Europe

University Campus STeP Ri Slavka Krautzeka 83/A 51000 Rijeka, Croatia Phone: +385 (51) 770 447 Fax: +385 (51) 686 166 www.intechopen.com

#### InTech China

Unit 405, Office Block, Hotel Equatorial Shanghai No.65, Yan An Road (West), Shanghai, 200040, China 中国上海市延安西路65号上海国际贵都大饭店办公楼405单元 Phone: +86-21-62489820 Fax: +86-21-62489821 © 2012 The Author(s). Licensee IntechOpen. This is an open access article distributed under the terms of the <u>Creative Commons Attribution 3.0</u> <u>License</u>, which permits unrestricted use, distribution, and reproduction in any medium, provided the original work is properly cited.

# IntechOpen

## IntechOpen